

SERVICE LETTER NO. 76-2
"FAA DOA EA-4 APPROVED"L
E
T
T
E
R

DATE: February 16, 1976

SUBJECT: VENDOR SERVICE PUBLICATIONS

SERIALS AFFECTED: All Model AA-1, AA-1A, AA-1B, AA-5, AA-5A and AA-5B.

TIME OF COMPLIANCE: As indicated in each publication.

Attached for your service information files, are copies of vendor service publications covering the items listed below. It is recommended that compliance with these publications be made as called out in the individual service bulletin, letter or instruction.

- ITEM 1. Lycoming Service Bulletin No. 369B, Engine Inspection After Overspeed or Overboost.
- ITEM 2. Lycoming Service Bulletin No. 385C, Oil Pump Impeller and Drive Replacement.
- ITEM 3. Lycoming Service Letter No. L179A, Factory Policy for Prorated Engine Replacement.
- ITEM 4. Lycoming Service Letter No. L185, The Use of Higher Octane Aviation Fuel, 100 LL Blue or 100 Green, for Engines Rated for 80/87 Octane Fuel.
- ITEM 5. Lycoming Service Instruction No. 1009V, Recommended Overhaul Periods.
- ITEM 6. Lycoming Service Instruction No. 1042J, Factory Approved Spark Plugs.
- ITEM 7. Lycoming Service Instruction No. 1070G, Specified Fuel.

GRUMMAN AMERICAN AVIATION CORPORATION

REB:jmz

Distribution (01)