



Gulfstream American

SERVICE LETTER NO. 79-2  
"FAA (DER) APPROVED"

DATE: 16 February 1979  
SUBJECT: CARBURETOR MIXTURE CONTROL RETAINER  
MODELS AFFECTED: AA-5B  
SERIALS AFFECTED: All AA-5B Aircraft  
TIME OF COMPLIANCE: At next carburetor overhaul or sooner at owner's discretion

GENERAL

Attached for your Service Publication files is a copy of Avco Lycoming Service Instruction No. 1370. To determine if aircraft is affected by this Publication, a visual inspection will be required to see if the retainer, Part No. 55-A239, has been incorporated. On AA-5B model aircraft, this can easily be accomplished by opening the upper right engine cowl and viewing the mixture control assembly. If not incorporated, it is recommended that the compliance with this Publication be accomplished within the specified time.

PARTS INFORMATION

Parts necessary for compliance with this Publication are available through authorized Avco Lycoming Distributors. Parts will not be made available through Gulfstream American Corporation.

As this is a product improvement, no parts or labor credit will be allowed.

GULFSTREAM AMERICAN CORPORATION

A handwritten signature in cursive script, appearing to read 'R. E. Belles'.

R. E. Belles, Director  
Light Aircraft Customer Service

REB:rjm

ATTACHMENT: Avco Lycoming Service Instruction No. 1370