



American General  
Aircraft Corporation

# SERVICE

LETTER

SERVICE LETTER No. 93-1

DATE: FEBRUARY 9, 1993  
 SUBJECT: OUTBOARD BEARING BRACKET ASSEMBLY  
 MODELS AFFECTED: AA-5, AA-5A, AA-5B  
 TIME OF COMPLIANCE: NONE - PROVIDED FOR INFORMATION ONLY

GENERAL:

We have received reports that there has been some confusion concerning the outboard aileron bearing support brackets. The aileron bearing support assembly as shown in the AA-5 Series Illustrated Parts Catalog is P/N 902010-501. This bearing bracket assembly underwent an engineering change dated 5-12-78 and was issued a new part number, 902010-504. This change was not reflected in the latest revision of the AA-5 Series Illustrated Parts Catalog or the AA-5 Series Maintenance Manual dated June 1, 1983. Both parts are considered to be serviceable, however, when replacement of the outboard aileron bearing bracket assembly is necessary, the -504 assembly with the collar on the inboard side should be installed and shimmed as required to obtain the specified aileron end play.

Very truly yours,

American General Aircraft Corporation

