

SERVICE LETTER NO. 75-5
"FAA DOA EA-4 APPROVED"

DATE: June 1, 1975
SUBJECT: VENDOR SERVICE PUBLICATIONS
SERIALS AFFECTED: All Model AA-1, AA-1A, AA-1B, AA-5 and AA-5B
TIME OF COMPLIANCE: As indicated in each publication.

Attached for your service information files, are copies of vendor service publications covering the items listed below. It is recommended that compliance with these publications be made as called out in the individual service bulletin, letter or instruction.

- ITEM 1. Narco Service Bulletin No. PDF-35-2, Circuit Change to Improve Operation of PDF-35 in Grumman American Aircraft Installations.
- ITEM 2. Lycoming Service Bulletin No. 369A, Engine Inspection After Overspeed or Overboost.
- ITEM 3. Lycoming Service Bulletin No. 385A, Oil Pump Impeller and Drive Replacement.
- ITEM 4. Lycoming Service Letter No. L-159C, Facilities for Cylinder Repair.
- ITEM 5. Lycoming Service Instruction No. 1230A, Sintered Iron Oil Pump Impellers.

N O T E

ITEM 6 APPLIES TO MODEL AA-5B AIRCRAFT ONLY; THEREFORE, LYCOMING SERVICE INSTRUCTION NO. 1307, CONNECTING ROD BOLT ASSEMBLY, WILL NOT BE ATTACHED TO COPIES OF THIS SERVICE LETTER THAT ARE SENT TO OWNERS OF MODEL AA-1, AA-1A, AA-1B AND AA-5 AIRCRAFT.

Very truly yours,

GRUMMAN AMERICAN AVIATION CORPORATION



Russ E. Belles
Customer Service Manager

REB:jmz

Distribution (01)