

SERVICE LETTER NO. 77-4
"FAA (DER) APPROVED"

**L
E
T
T
E
R**

DATE: December 30, 1977
SUBJECT: REPLACEMENT OF INDUCTION AIR FILTER ASSEMBLY
MODELS AFFECTED: AA5B-0001 thru AA5B-0549
TIME OF COMPLIANCE: At the next scheduled inspection, or sooner
at owner's discretion.

GENERAL

This Service Letter recommends the replacement of existing induction air filter assemblies with an improved air filter assembly. Service Kit No. 133 has been designed to provide the improved air filter assembly and for the installation of a detent to aircraft AA5B-0001 thru 0399 with the 5503005-501 induction air box assembly to secure the improved air filter assembly.

PARTS AVAILABILITY

Service Kit No. 133 is available through your authorized Grumman American Dealer at a suggested list price of \$54.76 (E).

CREDIT

Since the subject covered in this Service Letter is a design improvement and a normal service item, no parts or labor allowance will be available for compliance.

Very truly yours,

GRUMMAN AMERICAN AVIATION CORPORATION



R. E. Belles, Director
Light Aircraft Customer Service

REB:rjm

Distribution (02)