

DATE: June 21, 1978

SUBJECT: IMPROVED SUNVISOR MATERIAL

MODELS AFFECTED: All AA5A and AA5B aircraft equipped with optional sunvisors.

TIME OF COMPLIANCE: At the next scheduled inspection, or sooner at the owner's discretion.

GENERAL

At the 1978 Model Introduction Meetings, we announced new improved sunvisors for the 1978 Single Engine models. The new sunvisor provides improved durability and flexibility above previous designs by utilizing a new material for the Plexiglass visor. Due to production shortages, several early 1978 AA5A and AA5B aircraft were equipped with the earlier design. The new visor lens is a direct replacement for the earlier material. Replacement requires removing two (2) retaining screws from the existing sunvisor, removing the lens, and reinstalling the new lens with existing hardware.

PARTS AVAILABILITY

Visor lens, Part No. 5804034-15, are available through your authorized Grumman American Dealer at a suggested List Price of \$14.00 each (H). Two visors required per aircraft.

CREDIT INFORMATION

The new visor lens will be provided at no cost to the following aircraft, providing the aircraft was equipped with optional sunvisors:

AA5A-0523 thru AA5A-0556  
AA5B-0693 thru AA5B-0731

No labor allowance will be available for compliance.