

SERVICE LETTER NO. 78-3
"FAA (DER) APPROVED"

**L
E
T
T
E
R**

DATE: 27 September 1978
SUBJECT: NEW SERVICE AND ACCESSORY KITS
SERIALS AFFECTED: See below
TIME OF COMPLIANCE: As required

GENERAL

This is to advise of the availability of two new kits.

Service Kit 125 has been superseded by Service Kit 125A. The new kit consists of four sub-kits which may be purchased individually. The kits are effective for all single engine Grumman American aircraft except as noted.

Service Kit 125A-1 provides materials for the repair of limited bondline separations.

List Price....\$71.78 (E)

Service Kit 125A-2 provides materials for the repair of extensive bondline separations.

List Price...\$169.49 (E)

Service Kit 125A-3 provides materials for the installation of flight guard strips ("U" channels) on the trailing edges of applicable control surfaces.

List Price...\$135.15 (E)

Service Kit 125A-4 provides materials for the repair of separated upper cowl stiffener assemblies of AA5-0641 through 0834, all AA-5A, and all AA-5B aircraft.

List Price....\$76.38 (E)

Accessory Kit 130 provides for the addition of shock absorbers on the nose gear of the following aircraft:

<u>MODEL</u>	<u>SERIAL NUMBER</u>
AA-1	0001 and subsequent
AA-1A	0001 and subsequent
AA-1B	0001 and subsequent
AA-5	0001 and subsequent
AA-5A	0001 through 0282
AA-5B*	0001 through 0399

*AA-5B serials 0001 through 0399 must be equipped with the 5503005-519 Carburetor Air Induction Box to provide the necessary clearances for the installation of this kit.

Accessory Kit 130-1 is applicable to all AA-1, AA-1A, and AA-1B aircraft.

List Price...\$261.15 (E)

Accessory Kit 130-2 is applicable to AA5-0001 through 0640.

List Price...\$277.92 (E)

Accessory Kit 130-3 is applicable to AA5-0641 and subsequent, AA5A-0001 through 0282, and AA5B-0001 through 0399 aircraft.

List Price...\$336.16 (E)

GRUMMAN AMERICAN AVIATION CORPORATION



R. E. Belles, Director
Light Aircraft Customer Service

REB:mv