

SERVICE KIT NO. SK-131
"FAA DOA EA-4 APPROVED"

K
I
T

DATE: January 26, 1976
SUBJECT: CANOPY TRACK INTERCHANGE
(For use when 102450-501 Track Assembly is used to replace 102276-901 Track Assembly in the left hand position).
MODELS AFFECTED: All Model AA-1 and AA-1A; and AA1B-0001 thru AA1B-0550
WEIGHT AND BALANCE CHANGE: Negligible

PARTS LIST

<u>QUANTITY</u>	<u>PART NUMBER</u>	<u>DESCRIPTION</u>
1	5803007-22	Canopy Limit Placard

DESCRIPTION OF MODIFICATION

1. Removal of existing 803007-3 Canopy Open Placard and installation of 5803007-22 Canopy Limit Placard.
2. The 102450-501 Track Assembly may be used as a direct replacement for the 102276-901 Track Assembly when installed in the right hand position; however, the 5803007-22 Canopy Limit Placard must be installed when the 102450-501 Track Assembly is used in the left hand position on the models affected listed above.

INSTALLATION INSTRUCTIONS

1. Remove the existing 803007-3 Canopy Open Placard and discard.

N O T E

CLEAN SURFACES THOROUGHLY WITH ISOPROPYL ALCOHOL PRIOR TO INSTALLING PLACARD.

2. Position 5803007-22 Canopy Limit Placard on the same surface that placard was removed from in step 1, however, placard arrow is to be located 11.00 ± .12 inches from the aft face of the windshield bow.

GRUMMAN AMERICAN AVIATION CORPORATION

Distribution (16)