

SERVICE BULLETIN NO. 161
"FAA (DER) APPROVED"

DATE: May 24, 1977

SUBJECT: NARCO SERVICE BULLETIN ELT-10 NO. 7
ELT-10 - INSPECTION FOR CORROSION

SERIALS AFFECTED: ALL GRUMMAN AMERICAN AIRCRAFT EQUIPPED
WITH NARCO ELT-10.

TIME OF COMPLIANCE: AS CALLED OUT IN NARCO SERVICE BULLETIN
ELT-10 NO. 7.

GENERAL

FAA Airworthiness Directive No. 77-02-08 has been issued against the subject ELT-10 and requires compliance to assure proper operation. Since this unit was optionally installed in a majority of the affected aircraft, compliance with the Narco Service Bulletin ELT-10 No. 7 must be accomplished within the compliance time indicated.

Attached is Narco Avionics Service Bulletin ELT-10 No. 7 that covers the inspection of the subject batteries and battery leads.

PARTS AVAILABILITY

Parts may be obtained from your nearest authorized Narco Avionics Center. Your local Grumman American Dealer can direct you to the Narco Avionics Center nearest you.

CREDIT INFORMATION

Parts and labor allowances shall be in accordance with Narco Service Bulletin ELT-10 No. 7.

No parts or labor allowances will be available from Grumman American for compliance with this Service Bulletin

GRUMMAN AMERICAN AVIATION CORPORATION

REB:rjm

Distribution (01)

© Copy 1977 Grumman American Aviation Corporation, Savannah, Ga.