



American Aviation Corporation
318 Bishop Road Cleveland, Ohio 44143

SERVICE

LETTER

SERVICE LETTER NO. 72-8A
(SUPERSEDES SERVICE LETTER NO. 72-8)

DATE: January 9, 1973
SUBJECT: Canopy Trim Retrofit
SERIALS AFFECTED: AA5-0002 through AA5-0154
TIME OF COMPLIANCE: At owner's discretion

General

Many dealers and owners have requested that the parts required to update the 1972 model AA-5 canopy interior trim to 1973 appearance be made available to the field.

Accessory Kit

To make the 1973 style canopy interior trim available to those owners who wish to incorporate this improvement, we have developed an Accessory Kit No. AK-124, (\$95.00 (E)), which contains all material required (not including headliners and pads), plus installation instructions. This kit may be installed at the owner's discretion and will be available on or before January 15, 1973.

Credit Allowance

A labor credit allowance of up to 4.0 hours at the dealer's prevailing shop rate will be available for installation of Accessory Kit No. AK-124. Work must be performed or authorized by an American Aviation Corporation Dealer or representative and a Warranty Claim Form No. AA-740 must be submitted prior to July 1, 1973 for credit allowance.

No parts credit will be available for kit installation or return of materials removed from affected aircraft.

Prices subject to change without notice.

Very truly yours,

AMERICAN AVIATION CORPORATION

Paul H. Seibert
Customer Service Manager

PHS:pr

Distribution (B)

NOTE: Revision "A" changes the Accessory Kit No. from AK-123 to AK-124.